

Figure 1. PSI coherence change (red indicates a strong coherence reduction) caused by the Darfield Earthquake on 3-Sep-2010 shown for a section of Christchurch, New Zealand, shown in Google Earth.




Figure 2. Map showing areas with visible liquefaction (red areas, determined in-situ) found on New Zealand government web-site (<http://data.govt.nz>). The green rectangle indicates the area shown in Figure 1.